

# MACHINERY ROW GUIDELINES

**PRI**SHOW



Machinery Row Exhibitors who order services over 208 volts or 480 volts of 100 amps up to 200 amps will have the pictured transformer located inside their booth space. Anything ordered over 200 amps could require (2) transformers.



Machinery Row Exhibitors who order services up to 208 volts or 480 volts of 100 amps will have the pictured disconnect box located inside their booth space.

## TO ALL MACHINERY ROW EXHIBITORS

There is a possibility that even if your company did not order this level of power (208v or 480v), due to special power distribution needs for the show, exhibitors may still experience a large outlet/plug from the floor within or near your booth space ordered by a neighboring exhibitor.